

```
// PIC16F1829 EUSAT -> UART HEDDER  
void  init_UART(void);  
char  put_UART(unsigned char);  
char  get_UART(unsigned char*);  
void  puts_UART(unsigned char*);
```